



Global Barrier Services

SLIPCOAT IRC™ – Spray Cans Instructions for Use

USAGE INSTRUCTIONS:

- Make sure the surface to which **SLIPCOAT IRC™** is to be applied is as clean and dry as possible for the first application.
- Apply **SLIPCOAT IRC™** the same as you would spray paint. A light but thorough coating is all that is needed. DO NOT OVER APPLY. If you start to see drips, runs or pooling, stop spraying.
- Make sure that the corners and any other area where build-up might begin are well coated.
- If there is any debris on the surface, apply extra product around the edges. The **Slipcoat IRC™** will penetrate underneath and the debris will release over a short period of time.
- Re-apply as necessary.
- There is no waiting or 'curing' period required after application, equipment can be put directly into use following application.

It is important to remember that the longer **SLIPCOAT IRC™** is in use, the better it performs.

Extended usage allows the product to effectively penetrate the metal surface to which it is applied, creating a longer lasting, non-stick, protective barrier. Product performance will increase when in regular use and application frequency will decrease.

IMPORTANT

DO NOT apply to walkways, ladders, steps, hand-rails or any other surface/area that it may pose a slip hazard

DO NOT apply to lights, windows or other glass/translucent surfaces

DO NOT apply directly on engines, exhaust pipes or other extremely hot surfaces

Be aware of and clean up any overspray or spilled product

Product Support Contact Information:

Global Barrier Services, Inc.
1001 Avenida Pico, Suite C-433, San Clemente, CA 92673

Tel. 949 542 7440
Email. info@globalbarrierservices.com